

1

Install supplied slim mounting box or use other round conduit mounting box.

- a Note – silicone and screw caps must be used to maintain IP54 rating.
- b Refer to relevant AS/NZ standards for installation guidelines



2

Ensure gasket is present on outlet and has no twists or damage.
[High lighted in blue]



3

Connect wires into corresponding terminals in outlet.



4

Fit outlet to mounting box using supplied screws.
[must be fitted in the orientation shown to maintain IP rating]



5

Fit cover plate *[must be fitted to maintain IP54 rating]*



To remove cover plate, use flat head screwdriver to release securing tabs on both sides

