


Indoor LED batten LBS Series LBS620, LBS1240, LBS1550



INSTALLATION PROCEDURE

WARNING

- 1. Switch off before installation / maintenance.
- 2. Switch on only after complete installation and examination of the circuit.
- 3. Professional electrician for installation and maintenance only.






Turn Off power supply before starting any installation. Read instructions Θ check you have all the tools Θ accessories to complete the installation correctly.



HOW TO INSTALL


Step 1

Press the snap-on button and remove the cover.




Step 2

Connect the cable to terminal block. Fix the base to the ceiling.




Step 3

Slide the prefered CCT , connect the DC plug. Press the snap-on button and fix the cover to the base.



Step 4

Installation complete.





TECHNICAL SPECIFICATIONS

Technical Specifications:

| Rated Wattage | LBS620: 20W LBS1240: 40W LBS1550: 50W | |
|-----------------------------|---|--|
| Rated Input Voltage | AC230V | |
| Input Voltage | AC200-240V | |
| Efficiency | >85% | |
| Light Source | SMD | |
| SDCM | <5 | |
| CCT(K) | 3CCT: 3000K + 4000K + 5700K | |
| CCT Selection DIP Switch | YES | |
| CRI | Ra>80 | |
| Beam Angle | 120° | |
| LED Driver | Built-in Non-Dimmable | |
| Electrical Class | Class I | |
| IP Rating | IP20 | |
| IK Rating | IK08 | |
| Product Finishing(Base) | White RAL 9016 | |
| Materials of Optics | PC | |
| Materials of Housing | PC / IRON | |
| Lifetime (hr) | 50,000h | |
| Glow wire test | 750°C | |
| Operating Temp. | 10°C~45°C | |
| Storage Temp. | 0°C~65°C | |
| Installation | Surface mount | |
| | | |

Driver Specifications:

| Input Current | 20W: ≤0.12A 40W: ≤0.23A 50W: <0.28A |
|---|---|
| Power Factor | 0.9 |
| Efficiency | >85% |
| No load wattage | <0.5W |
| Short circuit protection Over voltage protection Over temperature protection | Pass |


Luminous Flux:

(lm) ±5%

| | LBS620 | LBS1240 | LBS1550 |
|-------|-----------|-----------|-----------|
| 3-CCT | 1800~2200 | 4000~4600 | 5200-5850 |




DIMENSIONS



Measurements in mm

| Model | Α | В | С |
|---------|------|----|----|
| LBS620 | 603 | 71 | 64 |
| LBS1240 | 1203 | 71 | 64 |
| LBS1550 | 1503 | 71 | 64 |



Measurements in mm

| Model | А | В |
|---------|------|------|
| LBS620 | 420 | 540 |
| LBS1240 | 900 | 1052 |
| LBS1550 | 1120 | 1352 |



Australia www.voltex.com P: 1300 722 275 E:sales@voltex.com

New Zealand www.voltex.com
P: 0800 55 66 33 E:sales@voltex.com